

| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|

Third Semester B.E. Degree Examination, December 2012
Material Science and Metallurgy

Time: 3 hrs.

Max. Marks:100

**Note: Answer FIVE full questions, selecting
at least TWO questions from each part.**

PART – A

- 1 a. Define atomic packing factor and calculate atomic radius and packing factor for BCC structure. (08 Marks)
- b. With a neat sketch, explain the line dislocation. (06 Marks)
- c. State and explain the first Fick's law of diffusion. (06 Marks)
- 2 a. With the help of a neat schematic conventional stress-strain diagram for mild steel under tension, explain clearly the behaviour of the material till fracture. (08 Marks)
- b. Explain non-linear elastic properties when a material is subjected to static tension. (06 Marks)
- c. What is work hardening? Explain the reasons for the same. (06 Marks)
- 3 a. Explain with neat figure ductile fracture using both stress-strain and stages of fracture. (08 Marks)
- b. What is mean by stress relaxation? Explain with figure. (06 Marks)
- c. With the help of sketch, discuss the different types of stress cycles which bring about fatigue failure. (06 Marks)
- 4 a. Explain with neat sketches the different stages of mechanisms of solidification. (08 Marks)
- b. Define solid solution. Explain the substitutional and interstitial solid solution. (08 Marks)
- c. Explain the factors governing the formation of substitutional solid solutions. (04 Marks)

PART – B

- 5 a. Draw and explain the Iron - Iron carbide equilibrium diagram and label all the points and fields. (10 Marks)
- b. Construct a phase diagram using the following data and label all the fields:

| | |
|---|---|
| Melting point of Ag = 961°C | Melting point of Cu = 1083°C |
| Eutectic temperature = 780°C | Eutectic composition = 28% Cu. |
| Max. solubility of Cu in Ag = 9% at 780°C | Max. solubility of Cu in Ag = 2% at 0°C |
| Max. solubility of Cu in Ag = 9% at 780°C | Max. solubility of Cu in Ag = 0% at 0°C |

 Determine the following:
 - i) Solidification start and end of temperature for 30% Ag alloy.
 - ii) Temperature at which a 15% Cu alloy has 50% liquid phase and 50% solid phase.
 - iii) Percentage composition of liquid and solid phase in 20% Ag alloy at 900°C. (10 Marks)
- 6 a. Draw the TTT diagram of austenite for eutectoid steel. Explain the various transformations product of austenite. (08 Marks)
- b. Discuss the process temperature range, microstructure of products and applications of stress relief annealing. (06 Marks)
- c. Explain with neat sketch induction hardening process. (06 Marks)

Important Note : 1. On completing your answers, compulsorily draw diagonal cross lines on the remaining blank pages.
2. Any revealing of identification, appeal to evaluator and/or equations written eg, 42+8 = 50, will be treated as malpractice.

- 7 a. Give the composition, structure and their applications of
i) S.G. Iron ii) Malleable Iron iii) Gray cast iron. **(08 Marks)**
- b. Name at least four important copper base alloys. Give composition microstructure and their applications. **(08 Marks)**
- c. Write a note on Al-Si alloys. **(04 Marks)**
-
- 8 a. Explain the term composite materials with examples. State their advantages and limitations of composites in practice. **(08 Marks)**
- b. Using neat sketch, explain the process of preparation of metal matrix composite using melting and casting method. **(08 Marks)**
- c. What are FRPs? Give at least four examples. **(04 Marks)**

* * * * *