

Third Semester B.E./B.Tech Degree Examination, Dec.2023/Jan.2024 Manufacturing Process

Time: 3 hrs.

Max. Marks: 100

Note: 1. Answer any FIVE full questions, choosing ONE full question from each module. 2. M : Marks, L: Bloom's level, C: Course outcomes.

		Module – 1	M	L	C
Q.1	a.	Define a gating system. Explain with sketches types of gating system.	10	L1	CO1
	b.	Explain with a neat sketch CO ₂ moulding process.	10	L2	CO1
		OR			
Q.2	a.	Define pattern and explain with a neat sketches any four pattern allowances.	10	L1	C01
	b.	Explain in detail the procedure to determine grain fineness number of greens and in foundry lab.	10	L2	C01
		Module – 2			
Q.3	a.	Explain with a neat sketch coreless induction furnace.	10	L2	CO2
	b.	Explain with a neat sketch cupola furnace.	10	L2	CO2
		OR	a.		<u> </u>
Q.4	a.	Explain with a neat sketch centrifugal casting process.	10	L2	CO2
	b.	Explain with neat sketches casting defects.	10	L2	CO2
		Module – 3			
Q.5	a.	Illustrate the following metal forming processes with neat sketches : i) Bending ii) Piercing iii) Blanking.	10	L2	CO3
	b.	Explain the following yield criteria : i) Tresca yield criteria ii) Von-Mises yield criteria.	10	L2	CO3
0	1	OR			1
Q.6	a.	Describe compound and progressive die processes.	10	L2	CO3
	b.	Explain the importance of temperature in metal forming and write the differences between hot working and cold working.	10	L2,1	CO3
	1	Module – 4			L
Q. 7	a.	Explain with neat sketches types of flames produced in OXY-Acetylene welding.	10	L2	CO4
	b.	Explain with a neat sketch OXY-Acetylene gas welding process.	10	L2	CO4
н	1	OR			1
Q.8	a.	Explain with a neat sketch MIG welding and mention its advantages, disadvantages and applications.	10	L2	CO4
91. 1	b.	Explain with a neat sketch Manual metal arc welding and also mention its advantages, disadvantages and applications.	10	L2	CO4
		Module – 5			
Q.9	a.	Explain with neat sketches welding defects.	10	L2	CO5
	b.	Explain with a neat sketch residual stresses in welded structures.	10	L2	CO5
a.		OR			•
Q.10	a.	Describe the following : i) Soldering	10	L2	CO5
		ii) Brazing.			
	b.	Explain with a neat sketch resistance welding process.	10	L2	CO5

* * * * *