

# CONTENTS

1. **Transmission of motion and power** 01-34
  1. Introduction 1; 2. Methods of drive 1; 3. Power of transmission elements 3; 4. Shafting 4; 5. Couplings for shafting 5; 6. Bearings for shafting 7; 7. Belt-drive 8; 8. Belting 13; 9. Pulleys 17; 10. Rope drive 19; 11. Chain drive 21; 12. Variable speed transmission 21; 13. Clutches 22; 14. Friction drive 23; 15. Gear drive 24; 16. Spur drive 25; 17. Helical gear 27; 18. Spiral gear 28; 19. Bevel gear 28; 20. Worm gear 30; 21. Rack and pinion 31; 22. Velocity ratio of toothed wheel 31; 23. Power transmitted by gearing 32; 24. Hydraulic system 33.
  
2. **Metal cutting and cutting tools** 35-82
  1. Introduction 35; 2. Types of cutting tools 36; 3. Orthogonal and oblique cutting 37; 4. Mechanics of cutting and chip formation 38; 5. Chip thickness ratio 40; 6. Velocity relationships 41; 7. Cutting forces in orthogonal cutting 42; 8. Stress in shear plane 45; 9. Work done and power required in cutting 45; 10. Cutting forces in oblique cutting 47; 11. Measurement of forces 49; 12. Types of chip 51; 13. Chip breakers 52; 14. Cutting-tool nomenclature 53; 15. Geometrical control of tool angles 55; 16. The cutting action of hand tools 56; 17. Cutting speeds and feeds 59; 18. Friction and heat sources in cutting 60; 19. Tool life and wear 62; 20. Machinability 69; 21. Cutting tool-materials 71; 22. Cutting fluids 76; 23. Economics of machining 79.
  
3. **The lathe** 83-182
  1. Introduction 83; 2. Function of lathe 83; 3. Types of lathe 83; 4. The size of a lathe 86; 5. Descriptions and functions of lathe parts 88; 6. The bed 88; 7. The headstock 90; 8. Tailstock or loose headstock 98; 9. Carriage 99; 10. Feed mechanism 104; 11. Thread cutting mechanism 110; 12. Lathe accessories and attachments 111; 13. Lathe operations 122; 14. Centering 123; 15. Turning 124; 16. Tapers and taper turning 126; 17. Eccentric turning 138; 18. Chamfering 139; 19. Thread cutting 139; 20. Facing 149; 21. Knurling 150; 22. Filing 151; 23. Polishing 151; 24. Grooving 151; 25. Spinning 152; 26. Spring winding 152; 27. Forming 152; 28. Drilling 153; 29. Reaming 154; 30. Boring 154; 31. Internal thread cutting 155; 32. Tapping 156; 33. Undercutting 156; 34. Parting-off 157; 35. Milling 157; 36. Grinding 158; 37. Cutting tools 158; 38. Forged tool 159; 39.

(xii) **ELEMENTS OF WORKSHOP TECHNOLOGY**

Brazed tipped tool 159; 40. Mechanically fastened tipped tool 161; 41. Solid tool 161; 42. Tool bit and tool holders 162; 43. Influence of tool angles 163; 44. Influence of tool height of tool angle 168; 45. Types of tool 169; 46. Cutting speed 177; 47. Feed 178; 48. Depth of cut 179; 49. Machining time 179; 50. Cutting tool signature 180.

4. **Capstan and turret lathes** 183-226  
1. Introduction 183; 2. Difference between a capstan and turret and an engine lathe 183; 3. Types of machine 185; 4. Difference between a capstan and a turret lathe 187; 5. Principal parts of capstan and turret lathes 188; 6. Capstan and turret lathe mechanism 191; 7. Capstan and turret lathe size 194; 8. Work holding devices 194; 9. Tool holding devices 198; 10. Capstan or turret lathe tools 210; 11. Capstan and turret lathe operations 217; 12. Turret tooling lay out 219; 13. Production of a hexagonal bolt 220; 14. Cutting speed, feed and depth of cut 223.
5. **Drilling machine** 227-278  
1. Introduction 227; 2. Types of drilling machine 227; 3. Portable drilling machine 228; 4. Sensitive drilling machine 228; 5. Upright drilling machine 229; 6. Radial drilling machine 230; 7. Gang drilling machine 232; 8. Multiple spindle drilling machine 232; 9. Automatic drilling machine 233; 10. Deep hole drilling machine 233; 11. The size of a drilling machine 233; 12. Upright drilling machine parts 234; 13. Radial drilling machine parts 239; 14. Work holding devices 240; 15. Tool holding devices 244; 16. Drilling machine operations 250; 17. Drilling machine tools 254; 18. Twist drill nomenclature 258; 19. Drill size 262; 20. Designation of drill 263; 21. Drill material 263; 22. Reamer 263; 23. Reamer nomenclatures 267; 24. Counterbore 271; 25. Countersinks and spot facers 271; 26. Taps 271; 27. Tap nomenclature 272; 28. Cutting speed 275; 29. Feed 276; 30. Depth of cut 276; 31. Machining time in drilling 277.
6. **Boring machines** 279-296  
1. Introduction 279; 2. Types of boring machine 279; 3. Horizontal boring machine 279; 4. Parts of a horizontal boring machine 282; 5. Size of a horizontal boring machine 283; 6. Boring machine mechanism 283; 7. Work holding devices for horizontal boring 284; 8. Horizontal boring machine operations 284; 9. Boring tool mountings for horizontal boring 285; 10. Boring tool 288; 11. Vertical

- boring machine 288; 12. Vertical boring machine parts 290; 13. Size of a vertical boring machine 291; 14. Work holding devices for vertical boring machine 291; 15. Vertical boring machine operations 291; 16. Vertical boring machine tools 293; 17. Precision boring machine 293; 18. Jog boring machine 293; 19. Methods of locating holes in jig boring 294; 20. Jig boring operations 295.
7. **Shaper** 297-324  
 1. Introduction 297; 2. Types of shapers 297; 3. Principal parts 299; 4. Shaper size 302; 5. Shaper mechanism 302; 6. Work holding devices 311; 7. Shaper operations 315; 8. Shaper tools 319; 9. Cutting speed, feed and depth of cut 321; 10. Machining time 323.
8. **Planing machines** 325-346  
 1. Introduction 325; 2. Types of planing machine 325; 3. Size of a planer 327; 4. Planing machine parts 328; 5. Planer mechanism 331; 6. Work holding devices 338; 7. Planer operations 340; 8. Planer tools 342; 9. Cutting speed, feed and depth of cut 342; 10. Machining time 343; 11. Shaper vs planer 343; 12. Safety on the planer 344.
9. **Slotting machines** 347-356  
 1. Introduction 347; 2. Types of slotting machine 347; 3. Slotter size 348; 4. Slotting machine parts 348; 5. Work holding devices 354; 6. Slotter operations 354; 7. Slotter tools 355; 8. Cutting speed, feed and depth of cut 356.
10. **Grinding machines** 357-396  
 1. Introduction 357; 2. Kinds of grinding 357; 3. Grinding machines 359; 4. Floor-stand and bench grinders 359; 5. Portable and flexible shaft grinders 360; 6. Swing frame grinders 360; 7. Abrasive belt grinders 361; 8. Cylindrical centre-type grinders 361; 9. Centreless grinders 364; 10. Internal grinders 366; 11. Surface grinders 367; 12. Tool and cutter grinders 371; 13. Special grinding machines 373; 14. Size and capacities of grinders 375; 15. Work holding devices and attachments 376; 16. Principal grinding operations 377; 17. Wet and dry grinding 378; 18. Allowance and tolerance for grinding 379; 19. The grinding wheel 379; 20. Abrasives 379; 21. Bonds and bonding processes 381; 22. Grit, grade and structure of wheels 383; 23. Wheel shapes and sizes 385; 24. Mounted wheels 386; 25. Standard marking system 386; 26. Selection of grinding

(xiv) **ELEMENTS OF WORKSHOP TECHNOLOGY**

wheels 387; 27. Mounting the grinding wheels 390; 28. Glazing and loading in wheels 391; 29. Dressing and truing grinding wheels 392; 30. Balancing grinding wheels 393; 31. Diamond wheels 394; 32. Cutting speed and work speed 394; 33. Feed 395; 34. Depth of cut 395; 35. Machining time in grinding 395.

**11. Milling machines**

**397-450**

1. Introduction 397; 2. Types of milling machine 397; 3. Principal parts 403; 4. Milling machine mechanism 406; 5. Size of milling machine 407; 6. Work holding devices 408; 7. Cutter holding devices 410; 8. Milling machine attachments 411; 9. Milling cutters 414; 10. Standard milling cutter 417; 11. Elements of a plain milling cutter 426; 12. Elements of a side milling cutter 429; 13. Elements of a face milling cutter 429; 14. Influence of tooth angles on cutter performance 430; 15. Sharpening milling cutters 433; 16. Milling cutter materials 434; 17. Fundamentals of the milling processes 434; 18. Milling machine operations 437; 19. Cutting speed, feed and depth of cut 445; 20. Number of cutter teeth 446; 21. Calculation of machining time 447; 22. Safety measures in milling 449.

**12. Gear cutting**

**451-486**

1. Gear cutting methods 451; 2. Formed cutter method 451; 3. Gear cutting by formed disc cutter 452; 4. Fundamental of spur gear milling by a formed disc cutter 452; 5. Spur gear proportions 453; 6. Indexing and dividing heads 454; 7. Indexing methods 457; 8. Spur gear milling operation 465; 9. Fundamentals of helical gear milling by a form disc cutter 466; 10. Fundamentals of bevel gear milling by form disc cutter 474; 11. Gear cutting by a formed end mill 481; 12. Gear cutting by a formed single point tool 481; 13. Gear cutting by shear speed process 481; 14. Broaching gear teeth 482; 15. Templet gear cutting process 482; 16. Generating methods 482; 17. Rack cutter generating process 483; 18. Pinion cutter generating process 483; 19. Gear hobbing 484; 20. Bevel gear generating process 486.

**13. Press and press work**

**487-512**

1. Introduction 487; 2. Types of presses 487; 3. Power press parts 490; 4. Power press driving mechanism 492; 5. Press size 494; 6. Press tools 494; 7. Methods of punch support 495; 8. Methods of die support 496; 9. Die accessories 497; 10. Types of dies and operations 499; 12. Press guards 511.

- 14. Jigs and fixtures** 513-532  
 1. Introduction 513; 2. Principles of jig and fixtures design 514; 3. Component 515; 4. The machine 515; 5. Location 515; 6. Methods of location 518; 7. Loading and unloading 521; 8. Clamping 521; 9. Types of clamps 522; 10. Power devices of clamping 525; 11. Clearance in a jig fixture 525; 12. Indexing arrangement 525; 13. Tool guiding and cutter setting arrangement 526; 14. Fool-proofing 527; 15. Ejection 527; 16. Swarf removal 528; 17. Rigidity and vibration 528; 18. Table fixing arrangement 528; 19. Safety devices 529; 20. Jig base, body or frame construction 529; 21. Jig and fixture types 530.
- 15. Broaching and sawing** 533-544  
 1. Introduction 533; 2. Broaches 533; 3. Broaching methods 536; 4. Broaching machines 537; 5. Broaching machine sizes 539; 6. Broaching fixtures 540; 7. Broaching operation 540; 8. Advantages and limitations of broaching 541; 9. Sawing 542; 10. Sawing machines 542; 11. Selecting a blade for sawing machine 543.
- 16. Surface finishing processes** 545-552  
 1. Introduction 545; 2. Lapping 545; 3. Honing 546; 4. Superfinishing 547; 5. Polishing 548; 6. Buffing 548; 7. Power brushing 549; 8. Tumbling 549; 9. Pickling and oxidizing 549; 10. Electroplating 550; 11. Hot dipping : Galvanizing 550; 12. Metal spraying 551; 13. Metallisation 551.
- 17. Erecting and testing machine tools** 553-562  
 1. Introduction 553; 2. Location 553; 3. Foundations 553; 4. Erection 554; 5. Testing 555; 6. Practical test 557; 7. Geometrical checks 557; 8. Measuring equipment for testing 559; 9. Magnitude and direction of tolerances 561; 10. Test charts 561.
- 18. Kinematic design of machine tools** 563-570  
 1. Fundamentals 563; 2. Fixation of limit speeds 565; 3. On the manner of layout 566; 4. On the number of output steps ( $Z$ ) 567; 5. Standard values of common ratio ( $\phi$ ) 568; 6. Inter-relation between  $Z$ ,  $\phi$ , and  $R_N$  569; 7. Some considerations for designing the speed structure 569.

(xvi) **ELEMENTS OF WORKSHOP TECHNOLOGY**

- 19. Numerical control of machine tools 571-604**  
1. Introduction, 571 ; 2. NC and its components 571; 3. Position and motion control in NC machine : open and closed loop 574; 4. Measuring systems for control 575; 5. NC machine – axis of motion 577; 6. Classification of NC system 578; 7. Tool positioning modes 580; 8. NC part programming 581; 9. Manual part programming 581; 10. Computer aided NC language 586; 11. Manual data input 592; 12. Preparation of processing instructions 592; 13. NC/CNC/DNC system 596; 14. NC machines 599.
- 20. Non-traditional machining 605-650**  
1. Introduction 605; 2. Classification of the machining Processes 605; 3. Abrasive jet machining (AJM) 608; 4. Ultrasonic machining (USM) 611; 5. Chemical machining (CHM) 615; 6. Electro-chemical machining (ECM) 618; 7. Electro-chemical grinding 628; 8. Electro-discharge Machining 631; 9. Electron-beam machining (EBM) 638; 10. Laser beam machining (LBM) 641; 11. Plasma arc Machining (PAM) 646; 12. Ion-beam machining (IBM) 648.
- 21. Transfer machining 651-660**  
1. Introduction 651; 2. Classification of transfer machines 651; 3. Main part of a transfer machine 654; 4. Auxiliary equipments 658; 5. Advantages and disadvantages 659. of control charts, 639; 10. Sampling inspection, 639.
- 22. Process planning and cost evaluation 661-676**  
1. Introduction 661; 2. Requirement for process planning 661; 3. Steps in process planning 662; 4. Planning the operations Sequence 665; 5. Process planning sheet 667; 6. An example of operation sequence 669; 7. Disadvantages of manual process planning 669; 8. Computer aided process planning 670; 9. Cost evaluation 672; 10. Standard costs 674; 11. Estimating labour costs 674; 12. Methods of costing 676.
- 23. CAD, CAM and CIM 677-690**  
1. Introduction 677; 2. Computer system 677; 3. Computer aided design 680; 4. Input and output devices of CAD-work 681; 5. Geometric modeling 682; 6. Computer-aided Manufacturing (CAM) 683; 7. Computer integrated Manufacturing 687.
- 24. Rapid Prototyping 691-700**  
1. Introduction 691 2. Basic principles 691 3. Rapid prototyping technologies 693. 4. Limitation of rapid prototyping 699. 5. Practical applications of Rapid prototyping 699.
- 25. Flexible Manufacturing Systems 701-714**  
1. Introduction 701, 2. Types of automation 702, 3. Flexibility examined 702. 4. Flexible manufacturing equipment 704. 5. Important items of FMS 709, 6. Advantages and disadvantages of FMS 612

**Appendix**

**A-1-A-4**

**Index**

**I-1-I-11**