## GBGS SCHEME

		T		r		1	Τ			
USN									15MEB405/15MA4	5
		l	1			ı	1	ł		

# Fourth Semester B.E. Degree Examination, June/July 2018 Machine Tools and Operations

Time: 3 hrs. Max. Marks: 80

Note: Answer any FIVE full questions, choosing one full question from each module.

#### Module-1

- 1 a. Define Machine tool. Give the classification of machine tools. (08 Marks)
  - b. Explain the constructional features of horizontal milling machine with a neat sketch.

(08 Marks)

#### OR

- 2 a. Define drilling. With a neat sketch explain bench drilling machine. (08 Marks)
  - b. Define grinding. Compare cylindrical grinding and center less grinding.

(08 Marks)

#### Module-2

- 3 a. Explain the following operations with simple sketches:
  - i) Turning
  - ii) Counter sinking
  - iii) Knurling
  - iv) Reaming.

(08 Marks)

- b. What are the different motions provided on:
  - i) Drilling machine
  - ii) Planer
  - iii) Grinding machine
  - iv) Shaping machine.

(08 Marks)

#### ΛR

4 a. With a neat sketch, explain thread cutting operation on lathe.

(08 Marks)

b. List and explain different machining parameters and related quantities on a lathe. (08 Marks)

## Module-3


5 a. Briefly explain the desirable properties of cutting fluids.

(08 Marks)

b. Calculate machining time for a work piece of 90mm diameter and 130mm length turned in 2 passes. If the approach length is 12mm and over travel is 5mm. Given cutting speed = 30m/min and feed 0.3 mm/rev. (08 Marks)

#### OR

- a. Briefly explain desirable properties or characteristics of an ideal cutting tool material. List various cutting tool materials. (08 Marks)
  - b. A shaping machine is used to machine a rectangular piece of 18cm long and 35cm width, with cutting speed being 26 m/min. Feed is 0.8 mm/cycle. Time for cutting to return stroke is 3:2. Find the time required to machine the whole surface. (08 Marks)



## Module-4

a. Explain the different types of chips produced during metal cutting with neat sketches.

(08 Mark:

b. With neat sketches explain the difference between orthogonal cutting and oblique cutting.

(08 Marks

### OR

8 a. What are the components of cutting force in turning a cylindrical job? (08 Mark

b. It is required to drill a 20mm diameter hole in a mild steel plate at a feed rate of 0.25 mm/rc and at a drill speed of 300rpm. Estimate the power required. Take machining constant C = 0.36 for mild steel material.

## Module-5

9 a. List the factors affecting tool life and briefly explain them. (08 Mark

- b. A tool life of 80 minutes is obtained at a speed of 30mpm and 8 minutes at 60mpr. Determine the following:
  - i) Tool life equation
  - ii) Cutting speed for 4 minute tool life.

(08 Mark

#### OR

10 a. Define tool wear. Explain crater wear and flank wear.

(08 Mark

b. What is machinability? List out the machinability criteria and explain them briefly.

(08 Marks